

| | | | | | |
|---------------------|---|----------------------------------|----------------------|---------------------------------|---|
| James Walker | Title: DEFECT REJECT CODES | Date: Aug 24, 2021 | Rev: 6 | Page: Page 1 of 1 | Document No: QPD81 Approved by: M.Richardson |
|---------------------|---|----------------------------------|----------------------|---------------------------------|---|

REASON FOR UPDATE: Owner of document changed & document review

ASSOCIATED DOCUMENTS:

| FAILURE MODE | DEFINITION |
|--|---|
| 1 BACKRIND | Split line defect, Tearing of rubber on press open or demould / deflash. Backrind: ragged "U" or "V" -shaped recess adjacent to split line. |
| 2 BAKE MARKS | Pressure marks, incorrectly stacked rings in bake house. |
| 3 BLISTER | Entrapped air. |
| 4 CHAMFER QUALITY | Chamfer irregular or narrow / wide chamfer |
| 5 DELAMINATION | Separation of fabric plies or rubberised fabric to rubber interface. |
| 6 DIMENSIONAL | Dimension outside tolerance. |
| 7 DIRT IN MATERIAL | Contamination / foreign material embedded in the surface |
| 8 FABRIC IN RUBBER | (Or rubber in fabric) Incorrectly positioned material in mould. |
| 9 FLASH SIZE (THICK) | Flash is too deep for a good trim. If depth OK then due to tool wear, if depth is up then probable excessive blank weight. |
| 10 FLASH STICKING ON COMPONENT | Self-explanatory? Moulding flash adhering to surface. |
| 11 FLOW MARKS | Thread-like recess, usually curved, of very slight depth in the un-flexed state, with normal surface texture and round edge. |
| 12 HARDNESS INCORRECT | Material hardness beyond specification. Too hard or soft. |
| 13 HOOK MARKS | Caused by extraction implement |
| 14 INDENTATION | Depression, usually irregular in form, can be caused by removal of inclusions .There are other potential causes depending on product type – not tool marks (see 29) |
| 15 INLAY INCORRECT SIZE / MISSING | Rubber inlay incorrectly measured / wrong size or missing. |
| 16 JOIN QUALITY | Wasting or narrowing at the join –inadequately bonded or angled 'flow marks' in join area . Can also be leaking of inflatable seal. |
| 17 LABORATORY TEST FAILURE | Seal component or material fails laboratory or other test. |
| 18 OSJ TABS MISALIGNED | OSJ tabs incorrectly aligned. |
| 19 MATERIAL INCORRECT | Incorrect compound or fabric used. |
| 20 METAL DAMAGE | Tool Damage – or bands incorrectly positioned, distorted / broken or buckled |
| 21 NON FILL / NOT UP | Random, irregular indentation with a coarser texture than the normal moulded surface. Incomplete fill, short weight |
| 22 OFFSET/ MISMATCH | Misalignment or differential sizing of tool halves resulting in a step at the split line. |
| 23 PLY MOVEMENT | Excessive deformation or twisting of fabric plies. |
| 24 SPLIT | Overstressed join/ split between different materials. |
| 25 SPRING COVERAGE | Polyolfin cover not fully covering spring area. |
| 26 SPRINGS MOVEMENT | Springs incorrectly positioned. |
| 27 SURFACE CONDITION | Complete or patchy areas of coarser texture due to cavity surface condition or rubber pre-vulcanisation ("Scorch") – various causes |
| 28 TRIMMING QUALITY | Excessive flash height or ragged/chipped trim. |
| 29 TOOL MARKS | Mould marks / Quality of tooling (Flats poor mould condition / raised marks) |